

SUMMARY

POLY-B PIPING, TORONTO, UN March 30, 2022

Report No. 0, v.0

www.inspectorsedge.com

SUMMARY

PLUMBING

This Summary outlines potentially significant issues from a cost or safety standpoint. This section is provided as a courtesy and cannot be considered a substitute for reading the entire report. Please read the complete document.

Plumbing

SUPPLY PLUMBING \ Water supply piping in building


Condition: • [Polybutylene](#)

This plastic piping was manufactured from the late 1970s to the mid 1990s. Failures in both the piping and the fittings have been documented. Many homeowners replace the piping to avoid the risk of water damage from a sudden failure.

Implication(s): Chance of water damage to structure, finishes and contents | Leakage

Task: Further evaluation by a specialist and replace when necessary

Time: As soon as practical




SUMMARY

SUMMARY

PLUMBING

Polybutylene pipe - compression (grip) fitting



Description

Supply piping in building: • PB (Polybutylene)

Limitations

General: • The extent of the polybutylene piping was not determined.

Recommendations

SUPPLY PLUMBING \ Water supply piping in building


1. Condition: • [Polybutylene](#)


This plastic piping was manufactured from the late 1970s to the mid 1990s. Failures in both the piping and the fittings have been documented. Many homeowners replace the piping to avoid the risk of water damage from a sudden failure.

Implication(s): Chance of water damage to structure, finishes and contents | Leakage

Task: Further evaluation by a specialist and replace when necessary

Time: As soon as practical





END OF REPORT