

EXTERIOR

DOWNSPOUT DISCHARGE TOO CLOSE TO HOUSE, Toronto, ON March 30, 2022

Report No. 0, v.0

www.inspectorsedge.com

EXTERIOR

Description

Gutter & downspout material: • [Aluminum](#)

Recommendations

ROOF DRAINAGE \ Gutters

1. Condition: • Discharge too close to building

Implication(s): Chance of water damage to structure, finishes and contents

Task: Improve

Time: As soon as practical

END OF REPORT