

SUMMARY

GALVANIZED STEEL SUPPLY PLUMBING, TORONTO, ON March 30, 2022

Report No. 0, v.0

www.inspectorsedge.com

SUMMARY

PLUMBING

This Summary outlines potentially significant issues from a cost or safety standpoint. This section is provided as a courtesy and cannot be considered a substitute for reading the entire report. Please read the complete document.

Plumbing

SUPPLY PLUMBING \ Water supply piping in building


Condition: • [Galvanized steel](#)

This piping is beyond its normal service life. The interior is typically corroded reducing water pressure and volume. Eventually the pipe walls fail and flooding occurs.

Implication(s): Reduced water pressure and volume

Task: Replace

Time: As soon as practical



Description

Supply piping in building: • [Galvanized steel](#)

Limitations

General: • The extent of the galvanized steel piping was not determined.

Recommendations

SUPPLY PLUMBING \ Water supply piping in building


1. Condition: • [Galvanized steel](#)

This piping is beyond its normal service life. The interior is typically corroded reducing water pressure and volume. Eventually the pipe walls fail and flooding occurs.

Implication(s): Reduced water pressure and volume

Task: Replace

Time: As soon as practical



END OF REPORT