

# SUMMARY

CAST IRON WASTE PIPING, TORONTO, UN March 30, 2022

Report No. 0, v.0

[www.inspectorsedge.com](http://www.inspectorsedge.com)

SUMMARY

PLUMBING

This Summary outlines potentially significant issues from a cost or safety standpoint. This section is provided as a courtesy and cannot be considered a substitute for reading the entire report. Please read the complete document.

## Plumbing

### **WASTE PLUMBING \ Drain piping - performance**

**Condition:** • Cast iron

The cast iron waste piping is near the end of its service life and is prone to rusting through or splitting. The replacement may be required soon.

**Task:** Replace

**Time:** When necessary or when remodeling

# PLUMBING

CAST IRON WASTE PIPING, TORONTO, UN March 30, 2022

Report No. 0, v.0

[www.inspectorsedge.com](http://www.inspectorsedge.com)

SUMMARY

PLUMBING

## Description

Waste and vent piping in building: • [Cast iron](#)

## Limitations

**General:** • The extent of the polybutylene piping was not determined.

## Recommendations

### **WASTE PLUMBING \ Drain piping - performance**

**1. Condition:** • Cast iron

The cast iron waste piping is near the end of its service life and is prone to rusting through or splitting. The replacement may be required soon.

**Task:** Replace

**Time:** When necessary or when remodeling

**END OF REPORT**