

SUMMARY

NO ACCESS TO ATTIC/ROOF SPACE, TORONTO, UN March 30, 2022

Report No. 0, v.0

www.inspectorsedge.com

SUMMARY

STRUCTURE

INSULATION

0123456789 0123456789 0123456789 0123456789 0123456789 0123456789 0123456789 0123456789 0123456789
0123456789 0123456789 0123456789 0123456789 0123456789 0123456789 0123456789 0123456789 0123456789
0123456789 0123456789 1

[Default text for insert](#)

Structure

RECOMMENDATIONS \ General

Condition: • No access to attic

Location: Attic

Task: Inspect,Provide Access

Time: As soon as practical

thanks for choosing ace!

[Default text for insert](#)

SUMMARY

STRUCTURE

INSULATION

Description

Roof and ceiling framing: • Not visible

Limitations

Attic/roof space: • No access

Recommendations

RECOMMENDATIONS \ General

1. Condition: • No access to attic

Location: Attic

Task: Inspect, Provide Access

Time: As soon as practical

INSULATION AND VENTILATION

NO ACCESS TO ATTIC/ROOF SPACE, TORONTO, ONTARIO March 30, 2022

Report No. 0, v.0

www.inspectorsedge.com

SUMMARY

STRUCTURE

INSULATION

Description

Attic/roof insulation material:

- Not determined
- lack of access

Attic/roof insulation amount/value: • Not determined

END OF REPORT